



1/16

FIG.1




2/16

FIG.2



3/16

FIG.3




4/16

FIG.4


	Icq Const.			Icq Control		
Pout [dBm]	Icq [mA]	PAE [%]	ACPR [dBc]	Icq [mA]	PAE [%]	ACPR [dBc]
10	18	12.47	-62.67	2	28.81	-40.87
11	18	18.06	-65.03	3	32.00	-41.77
12	18	21.07	-62.69	3	35.97	-40.24
16	18	36.81	-39.37	7	47.87	-38.19
19	18	42.21	-40.89	7	45.26	-38.98
20	18	46.47	-38.90	14	48.11	-38.56
21	18	49.77	-40.92	14	51.02	-39.56
24	18	50.44	-38.66	14	50.78	-38.37
25	18	48.99	-38.87	18	48.99	-38.87
26	18	45.42	-40.08	18	45.42	-40.08

FIG.5



6/16

FIG.6



7/16

FIG.7





FIG. 7, 8,
 [1]

FIG.8



8/16

FIG.9






FIG.10




9/16

FIG.11




10/16

FIG.12



11/16

FIG.13



12/16

FIG.14





FIG.15



13/16

FIG.16





FIG.17



14/16

FIG.18






FIG.19



15/16

FIG.20




Con + Coff = Constant



Almost Unchanged

16/16

FIG.21



Con/Coff = Changed by -16 deg. at Con/Coff = 0.4pF/1.9pF
Con/Coff = Changed by -44 deg. at Con/Coff = 0.8pF/1.5pF
Con/Coff = Changed by -64 deg. at Con/Coff = 1.2pF/1.1pF